

List of Figures	Page
Chapter One	
Figure 1.1 McWay 1984.....	2
Figure 1.2 McWay 1991 looking north.....	2
Figure 1.3 McWay 1991.....	3
Figure 1.4 Mcway 1992 from the beach looking up at main gully.....	3
Figure 1.5. Mcway 1993. Note the evolution of gully on right side of slide in this photograph and the following figure.....	4
Figure 1.6. Mcway 1995.....	4
Figure 1.7. McWay 1997 pre- slope restoration.....	5
Figure 1.8. Mcway 1997 post- slope restoration.....	5
Figure 1.9. McWay site preparation.....	6
Figure 1.10. Winter 1999-2000.....	7
Figure 1.11. Spring 2000.....	7
Figure 1.12. Bare slope of 1998.....	7
Figure 1.13. Vegetation of upper main gully in spring 2000.....	8
Figure 1.14. The main gully pictured from the beach. Arrow marks the top of the point at which the smaller, more unstable gully begins on the slope.....	8
Figure 1.15. A close up of the top of the smaller gully showing the willows in the more stable area, and bare soils below.....	8
Figure 1.16. Main gully from the beach.....	9
Figure 1.17. Two views of hydroseeded slope.....	9

Figure 1.18. Hydroseed truck.....	10
Figure 1.19. Sediment plume from rain-washed slope.....	10
Figure 1.20. Front face of McWay, before and after rain. Time series photographs showing erosional events before and after rain in February 2000.....	11
Figure 1.21. Pampas grass on site.....	12
Figure 1.22. Loose straw cast over slope, winter 1999-2000.....	13
Figure 1.23. Photo monitoring Point 1.....	14
Figure 1.24. Map of photo monitoring points at McWay.....	15
Figure 1.25. Photo monitoring Point 2, left 1998, right 2000.....	15
Figure 1.26. Photo monitoring Point 3, left 1998, right 2000.....	15
Figure 1.27. Photo monitoring Point 4, left 1998, right 2000.....	16
Figure 1.28. Photo monitoring Point 5, left 1998, right 2000.....	16
Figure 1.29. Photo monitoring Point 6, left 1998, right 2000.....	16
Figure 1.30. Photographic monitoring of plots.....	17
Chapter Two	
Figure 2.1. Erosion assessment ranking for upslope (East of highway).....	20
Figure 2.2. Erosion assessment ranking for down slope (West of highway).....	21
Figure 2.3. Regional landslide and erosion site map for the Big Sur Coast.....	22
Figure 2.4. Little Sur South, February 2000.....	24
Figure 2.5 Detail of slope from road looking south.....	26

Figure 2.6. Cracks evident in pavement need monitoring.....	26
Figure 2.7. Sycamore Draw, February 2000.....	28
Figure 2.8. Picture on left shows the pampas grass growing on site, and the picture on the right shows bare surface soil that needs to be stabilized.....	30
Figure 2.9. Long shot looking north.....	30
Figure 2.10. View of upslope showing pampas grass and bare soil.....	30
Figure 2.11. Rat Creek, February 2000.....	32
Figure 2.12. Pictures showing bare unstable soil and pavement cracks. Surface water flow may be adding to erosion problems.....	34
Figure 2.13. Long-shot looking north showing up slope.....	34
Figure 2.14. Vista Point South Big Creek, February 2000.....	36
Figure 2.15. Picture looking north showing sidecast with no vegetation present.....	38
Figure 2.16. Picture showing bare soils and invasive weeds at the highway edge, looking south.....	38
Figure 2.17. View of unvegetated berm.....	38
Figure 2.18. North Vicente Creek Bridge, February 2000.....	40
Figure 2.19. Recent road repair and sidecast with little erosion protection.....	42
Figure 2.20. Sidecast, unstable soil, and invasive weeds.....	42
Figure 2.21. Picture taken in early January 2001 shows very high berm obscuring views from the highway and pullout.....	42
Figure 2.22. Grandpa's Elbow, February 2000.....	44

Figure 2.23. Sidecast left in early Spring 2000. As the year progressed, more sidecast was left behind due to road repairs at another location.....	46
Figure 2.24. Detail photos on the damage of surface water. Top two photos show the wattles need repositioning. Bottom photo was taken on the downslope (west side) of highways and shows surface water rill, and in the background, used Dry Water wells that need to be removed.....	47
Figure 2.25. Willow Springs, February 2000.....	49
Figure 2.26. Looking downslope facing south. View of large unvegetated gully.....	51
Figure 2.27. Looking downslope facing south near road structure. Note irrigation lines, rebar, and other materials that may need removal. Vegetation seems well established at this previous restoration site.....	51
Figure 2.28. Looking downslope and north showing bare soil, eucalyptus and pampas grass.....	51
Figure 2.29. Gray Slip, February 2000.....	53
Figure 2.30. Site photo showing storage of loose soil material. Revegetation work needs to continue to stop surface erosion.....	55
Figure 2.31. Gray Slip upslope showing bare slope.....	55
Figure 2.32. Redwood Gulch, February 2000.....	57
Figure 2.33. This site is large in scale. The top photo pictures the upslope, and the boxed area is shown enlarged in the bottom photo.....	59
Figure 2.34. Redwood Gulch downslope looking north. Note pampas grass and old irrigation line.....	59
Figure 2.35. Salmon Creek South, February 2000.....	61
Figure 2.36. Slope pictured from Spring, 2000. Slope continued to erode until it closed the south bound lane. Roadway is under construction currently.....	63

Figure 2.37. Hurricane Point, February 2000.....	65
Figure 2.38. South Forty, February 2000.....	66
Figure 2.39. Little Sur, February 2000.....	67
Figure 2.40. McWay North, February 2000.....	68
Figure 2.41. McWay, February 2000.....	69
Figure 2.42. Blue Slide, February 2000.....	70
Figure 2.43. Limekiln, February 2000.....	71
Figure 2.44. Cape San Martin, February 2000.....	72
Chapter Three	
Figure 3.1. Schematic of berm restoration.....	73
Figure 3.2. Schematic of sidecast and overcast for slopes greater than 20 foot run.....	74
Figure 3.3. Schematic of energy dissipator.....	75
Figure 3.4. Schematic of slope breaker.....	76
Figure 3.5. Schematic of slope breaker with jute netting and straw.....	77
Figure 3.6. Schematic of planting techniques.....	78
Figure 3.7. Schematic of willow planting.....	79
Figure 3.8. Schematic of willow wattle installation.....	80
Figure 3.9. A willow mattress.....	80
Figure 3.10. Schematic of silt fence installation.....	81